5.6.10 MAIN INPUT POWER CONNECTIONS



Note 1 FUSE 2 and contactor are not required if the input power line is neutral.
Note 5: All AC line wires should be a twisted pair.
Note 6: The ground of the drive and motor best minimizes ground currents and noise when connected in a "star point" configuration.
Note 10: Cables should be properly bonded to the back panel and implemented as close to the drive side of the cable as possible for effective grounding. If bonding is installed, the shield on the cable end need not be connected to the "star point" configuration. Only connect the shild on one end of the cable (preferably on the drive side).
Note 13: See the SERVO**STAR** Cx Hardware Specifications and Bus Module Hardware Specifications for wire gauge and ferule sizes.
Note 14: See CE Filtering Techniques for further information.

5.6.11 C8 REMOTE ENCODER INPUT