



Spindle nut is PN 1438  
 Drawbar bushing is PN 1656

LittleMachineShop.com <small>© 2004 LittleMachineShop.com. All rights reserved</small>		
<b>1407 Spindle, R8</b>		
Revision 0	Scale 1:1	Sheet 1 of 1